

General Environmental Incident Summary

Incident: 810 **Date/Time Notice:** 1/3/2006 0833 **DEM Incident No:**
Responsible Party: Bobcat Company
Date Incident: 1/1/2006 **Time Incident:** 0425 **Duration:** 2 hours
County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 3 **Qtr:**
Lat: 46.80198 **Long:** -100.76260 **Method:** Derived from TRS
Location Description: 521 S. 22nd Street, Bismarck (Spill on 26th Street side of Bobcat Factory).
Majority of spill contained inside factory building.

Submitted By: Darrell Hellman **Affiliation:**

Address:

City: **State:** **Zip:**

Received By: Kris Roberts

Contact Person: Darrel Hellman
521 South 22nd Street
Bismarck, ND 58506-5556

Distance Nearest Occupied Building: 0 Feet

Type of Incident: pump leak, valve malfunction

Description of Released Contaminant: Non-Hazardous E-Coat Paint Mixture (10 % product, 90% water)

Volume Spilled: 28000.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Yes **Reported to NRC:** No

Cause of Incident:

Valve malfunction on 1" line served by 150 GPM recirculation pump. 12,000 gal sump pit then overfilled. Estimating 10,000 gallons got outside building onto sod and gravel parking lot.

Risk Evaluation:

none

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Surface soils impacted only. Paint ingredient is "Vectrogard 720 Gray Feed". Balance is Reverse Osmosis treated city water.
None of the spilled material reached either city storm or sanitary sewer system.

Action Taken or Planned:

8 truckloads of sand brought in to contain and absorb fluids outside the building. Earthmovers of Minot called in to haul 15 truckloads of the sand and 4-6" of sod and gravel and 40 bags of spread 'floor dry' to Clean Harbors in Sawyer. Soil samples will be submitted today to MVTL after determining parameters to analyze for from Valspar Company

Wastes Disposal Location: Clean Harbors, Sawyer.

Agencies Involved:

